

# Oil Field Environmental Incident Summary

**Incident:** 20130720113448

**Date/Time of Notice:** 07/20/2013 11:02

**Responsible Party:** Ed Pottorff

**Well Operator:** FIDELITY EXPLORATION & PRODUCTION COMPANY

**Well Name:** SCHWARTZ 14-2H

**Field Name:** DUTCH HENRY BUTTE

**Well File #:** 22959

**Date Incident:** 7/19/2013

**Time Incident:** 14:30

**Facility ID Number:**

**County:** STARK

**Twp:** 140

**Rng:** 97

**Sec:** 2

**Qtr:**

**Location Description:**

**Submitted By:** Ed Pottorff

**Received By:**

**Contact Person:**

1700 LINCOLN ST STE 2800  
DENVER, CO 80203-4546

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pump Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

**Areal Extent:**

***Potential Environmental Impacts:***

***Action Taken or Planned:***

Recycling pump was shut down and valve to suction line was closed while the VIC clamp bolts were tightened. Oil was cleaned up by a VAC truck.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 7/22/2013    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release remained on location, within the diking, according to the report.

---

***Date:*** 7/25/2013    ***Status:*** Inspection

***Author:*** Espe, Brady

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

The weather was 69°F, with a northwest wind at 10-15 mph. The spill did not appear to leave the pad and stayed within the dike system. Did not see any issues, no follow-up required at this time.